


INSTRUCTIONS & INFORMATION



623701

(Sheave height spacers are no longer included in Spindle Assemblies)



Item No.	Order No.	Description	Item No.	Order No.	Description
1	623733	Blade Spindle Assembly	18	721167	Shield-Bearing (not used on item 7)
2	623735	Blade Spindle Assembly	19	110081	Bearing-Ball
3	623736	Blade Spindle Assembly	20	604413	Housing Assy-Spindle Alum
4	623737	Blade Spindle Assembly	21	903643	Spacer-Bearing Deep Spindle
5	623738	Blade Spindle Assembly	22	604774	Spindle Shaft Assembly
6	623742	Blade Spindle Assembly	23	421200	Washer - Fiber
7	623745	Blade Spindle Assembly	24	257061	Washer
8	623747	Blade Spindle Assembly	25	257057	Washer - Hardened-Blade Spindle
9	623757	Blade Spindle Assembly	26	243583	Hex Bolt-Flange - Grade 8
10	623762	Blade Spindle Assembly	27	247141	Round Head Bolt - Ribbed Neck
11	243331	Hex Bolt	28	257055	Washer
12	257041	Washer-Cupped	29	423680	Deflector Cone
13	* 282607	Spacer	30	* 281583	Key Square
14	* 282615	Spacer	31	* 281582	Key Square
15	* 282630	Spacer	32	* 281580	Key Square
16	* 257104	Washer	33	* 281575	Key Square
17	259305	Set Screw	34	253035	Nut - Whiz
			35	280745	Fitting-Grease (Zerk)

* NOT INCLUDED WITH SPINDLE ASSEMBLIES

NOTE: See page 2 for Blade Spindle Assemblies 6-10