

# INSTRUCTIONS & INFORMATION



## DRIVE UPDATE 512 SNOWTHROWER SPEED-UP KIT

Part Number 604315

To be used for 512 snowthrower with 11 tooth drive sprocket.

### UPDATE INSTRUCTIONS

(refer to illustration)

1. Remove the chain shield from the side of the auger housing.
2. Loosen the idler sprocket and remove the drive chain.
3. Remove the existing drive sprocket and replace it with the new 13 tooth sprocket. Align with the other sprockets.
4. Remove pins from chain so that it is 48 pins long.
5. Install drive chain on sprockets.
6. Tighten idler sprocket to the proper chain tension.
7. Install chain shield.

