

# PowerFold®




## Part No. 163161

3348PF  
3452PF  
3461PF  
3452RPF  
3461RPF  
3472LS  
3472PF  
3472LSR  
3552  
3561  
3572

Actuator must be against stops  
when deck is in the down  
position. Failure to support  
actuator may cause rod to bend.  
162173


## Part No. 162173

3348PF  
3452PF  
3461PF  
3452RPF  
3461RPF  
3472LS  
3472PF  
3472LSR  
3552  
3561  
3572



## Part No. 165430

3348PF  
3452PF  
3461PF  
3452RPF  
3461RPF  
3472LS  
3472PF  
3472LSR  
3552  
3561  
3572



## Part No. 162205

(No Step - Actuator)  
3472LS  
3472PF  
3472LSR  
3572