

PowerFold®




Part No. 163161

3348PF
3452PF
3461PF
3452RPF
3461RPF
3472LS
3472PF
3472LSR
3552
3561
3572

Actuator must be against stops
when deck is in the down
position. Failure to support
actuator may cause rod to bend.
162173


Part No. 162173

3348PF
3452PF
3461PF
3452RPF
3461RPF
3472LS
3472PF
3472LSR
3552
3561
3572



Part No. 165430

3348PF
3452PF
3461PF
3452RPF
3461RPF
3472LS
3472PF
3472LSR
3552
3561
3572



Part No. 162205

(No Step - Actuator)
3472LS
3472PF
3472LSR
3572