

PowerFold®




Part No. 163161

3348PF
3452PF
3452RPF
3461PF
3461RPF
3472LS
3472LSR
3472PF
3552
3561
3572
3661
3761
526V/52

Actuator must be against stops
when deck is in the down
position. Failure to support
actuator may cause rod to bend.
162173


Part No. 162173

3348PF
3452PF
3452RPF
3461PF
3461RPF
3472LS
3472LSR
3472PF
3552
3561
3572
3661
3761
526V/52



Part No. 165430

3348PF
3452PF
3452RPF
3461PF
3461RPF
3472LS
3472LSR
3472PF
3552
3561
3572
3661
3761
526V/52



Part No. 162205

(No Step - Actuator)

3472LS
3472PF
3472LSR
3572
3661
3761