

PowerFold®

EQUIPPED WITH
PowerFold


Part No. 163161

3348
34PF
35PF
3661
3761
524V
526V

Actuator must be against stops
when deck is in the down
position. Failure to support
actuator may cause rod to bend.
162173


Part No. 162173

3348
34PF
35PF
3661
3761
524V
526V



Part No. 165430

3348
34PF
35PF
3661
3761
524V
526V



Part No. 162205

(No Step - Actuator)

3472
3572
3661
3761
524V