



Figure 2

Item No.	Order No.	Description
1	645111	Bracket – OC Discharge Base
2	645112	Bracket – OC Discharge Pivot
3	645652	Pivot – Discharge Control
4	725117	Tab – OC Discharge Plate
5	729943	Bracket – Discharge Lever Support
6	729947	Bracket – Discharge Lever Pivot "XL"
7	766105	Plate – Discharge Cover
8	774317	Strap – OC Discharge Linkage
9	774359	Lever – Discharge Control
10	775247	Arm – OC Discharge Control
11	780171	Rod – Linkage 12.25"
12	780651	Pin – OC Discharge Shield
13	820111	Hinge – Discharge Cover
14	822305	Pivot Bearing
15	833543	Shield – Discharge Cover
16	881095	Spacer .25"
17	422155	Handle Grip – Black
18	421200	Washer – Fiber .5 x 2.25
19	284406	Spring – Torsion
20	283381	Spring – Compression
21	265651	Rod End .312-24 Lt. Female
22	265615	Ball Joint .312-24 Thread
23	260608	Ring Cotter .054 x .375
24	257067	Washer .531 x 1.125
25	254444	Nut .312-24 Left Hand Thread
26	254441	Nut .312-24
27	253470	Nut .5-13 Nylon Insert
28	253450	Nut .312-18 Nylon Insert
29	253176	Whiz Bolt .25-20 x .5 Truss
30	253175	Whiz Bolt .25-20 x .75 Hex
31	253173	Whiz Bolt .25-20 x .5 Hex
32	253038	Whiz Nut .312-24 Hex
33	253035	Whiz Nut .312-18
34	253025	Whiz Nut .25-20
35	252821	Stud .312-18 x 1.25 3-Prong
36	243580	Bolt .5-13 x 2
37	243215	Bolt .312-18 x 1.5
38	243205	Bolt .312-18 x 1
39	243195	Bolt .312-18 x .75
40	243016	Bolt .25 x 625 Washer Head Tap
41	253172	Whiz Bolt .25-20 x .625 Hex